



Quick start for ThermaViewer and local alarm.

The ThermaViewer relay is energized with 12 VDC with the positive pole closest to the power supply.

The local alarm can be wired so that the strobe flashes or the strobe flashes and the siren sounds simultaneously.

NOTE: This alarm is very loud. You can test the alarm by going to the System parameter menu and setting the “Test the relay” to ‘YES’. This will trigger the relay for 1 second.